

JACK SANSAVER  
751 COOKE CANYON RD.  
E-burg WA, 98926

trouble shot AN17  
Re Fuse TRANSFORMER  
looks like ANIMAL  
got into mesh side

A200 J. Sauer

pd. By RAY

J. S.

check #  
1268

6-21-17

PHONE 253-606-6253 CELL