


USS Constitution


BOSTON, MASSACHUSETTS





MINI BUILDING BLOCKS

1710 PCS







1





2







3





4







5





6







7





8







9





10






11






12



- X2
- X4
- X2
- X2
- X2
- X2
- X8
- X2
- X2
- X2
- X11
- X12
- X8

13




- X9
- X18
- X4
- X2
- X2
- X2
- X2
- X6
- X2
- X1
- X6
- X2
- X2


14





X2

X2






15




16



- X6
- X4
- X2
- X2
- X2
- X2
- X2
- X2

17


- X2
- X2






- X1
- X5
- X3
- X4
- X23


- X30
- X2
- X16
- X20
- X4

18




19









20



21




22












23



24






25





- X30
- X2
- X16
- X20
- X4

26




- X24
- X2
- X13
- X17
- X4


28




- X4
- X1
- X1
- X2
- X1
- X1
- X4
- X15
- X1
- X1
- X2
- X2
- X1
- X2

27










29



30





31





- X24
- X2
- X13
- X17
- X4

32






33







34






35





36





For any issues regarding missing or defective pieces,
please contact Impact Photographics directly by e-mailing:
customerservice@impactphotographics.com

©IMPACT PHOTOGRAPHICS
4961 Windplay Drive • El Dorado Hills, CA 95762